

103 South Main Street, Ladd Hall  
Waterbury VT 05671-2306  
<http://www.dail.vermont.gov>  
Voice/TTY (802) 241-2345  
To Report Adult Abuse: (800) 564-1612  
Fax (802) 241-2358

April 4, 2011

Ms. Ursula Margazano, Administrator  
Burlington Health & Rehab  
300 Pearl Street  
Burlington, VT 05401

Dear Ms. Margazano:

Enclosed is a copy of your acceptable plans of correction for the Life Safety Code survey conducted on February 5, 2011. This accepted plan of correction reflects your plan of correction after the Informal Dispute Resolution results. Please post this document in a prominent place in your facility.

Sincerely,



Pamela M. Cota, RN  
Licensing Chief



DEPARTMENT OF HEALTH AND HUMAN SERVICES  
CENTERS FOR MEDICARE & MEDICAID SERVICES

RECEIVED  
Division of

APR 11

Licensing and  
Protection

PRINTED: 03/25/2011  
FORM APPROVED  
OMB NO. 0938-0391

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION	(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER:  475014	(X2) MULTIPLE CONSTRUCTION A. BUILDING 01 - 01 BUILDING B. WING _____	(X3) DATE SURVEY COMPLETED  02/15/2011
--	--	---	--

NAME OF PROVIDER OR SUPPLIER  BURLINGTON HEALTH & REHAB	STREET ADDRESS, CITY, STATE, ZIP CODE 300 PEARL STREET BURLINGTON, VT 05401
---	---

(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)	(X5) COMPLETION DATE
--------------------	--	---------------	---	----------------------

K 000 INITIAL COMMENTS

K 000

A life safety code survey was completed on 2/15/11. The following violations were identified.

K 017 NFPA 101 LIFE SAFETY CODE STANDARD SS=D

K 017

Corridors are separated from use areas by walls constructed with at least 1/2 hour fire resistance rating. In sprinklered buildings, partitions are only required to resist the passage of smoke. In non-sprinklered buildings, walls properly extend above the ceiling. (Corridor walls may terminate at the underside of ceilings where specifically permitted by Code. Charting and clerical stations, waiting areas, dining rooms, and activity spaces may be open to the corridor under certain conditions specified in the Code. Gift shops may be separated from corridors by non-fire rated walls if the gift shop is fully sprinklered.)  
19.3.6.1, 19.3.6.2.1, 19.3.6.5


K017

Storage area enclosure to include extension of wall to terminate at the underside of ceiling as required to resist passage of smoke.

Maintenance Svcs &/or designee 3-18-2011

K017 POC Accepted 4/11/11  
J. Bernard / AMCotURN

This STANDARD is not met as evidenced by:  
Based on inspection on 2/15/11, there is storage in a room off the corridor near the sprinkler room door. This space is open to the corridor.

LABORATORY DIRECTOR'S OR PROVIDER/SUPPLIER REPRESENTATIVE'S SIGNATURE 	TITLE Administrator	(X6) DATE 3/31/11
---	------------------------	----------------------

Any deficiency statement ending with an asterisk (\*) denotes a deficiency which the institution may be excused from correcting providing it is determined that other safeguards provide sufficient protection to the patients. (See instructions.) Except for nursing homes, the findings stated above are disclosable 90 days following the date of survey whether or not a plan of correction is provided. For nursing homes, the above findings and plans of correction are disclosable 14 days following the date these documents are made available to the facility. If deficiencies are cited, an approved plan of correction is requisite to continued program participation.